



1400MHz

DL580 G2




1600MHz

DL580 G2



1600MHz

DL580 G2




1400MHz


DL580 G2

Mixed ProLiant SAN


Pentium XEON MP
1400MHz 2P 201202-421 EU




Pentium XEON MP
1600MHz 2P 201203-421 EU



Pentium XEON MP
1600MHz 2P 201203-421 EU



Pentium XEON MP
1400MHz 2P 201202-421 EU



Part Number	Qty	Description
201723-B21	1	MSA1000 RAID Array 128MB Rack 4U
1.1	153506-B21	1 128MB Battery Backed Cache Upgrade
1.2	190209-B31	1 Modula M4314R single buss.14x 1.0"
1.2.1	232432-B22	14 72.8GB 10000r Ultra3 SCSI disk 1"
1.3	190209-B31	1 Modula M4314R single buss.14x 1.0"
1.3.1	232432-B22	14 72.8GB 10000r Ultra3 SCSI disk 1"
1.4	218231-B21	1 MSA1000 Redundant Controller
1.4.1	153506-B21	1 128MB Battery Backed Cache Upgrade
1.5	218232-B21	2 MSA1000 Fabric Switch, 6 port
1.6	221470-B21	1 MSA1000 2GB SFP-SW Tranceiver kit
1.7	232432-B22	14 72.8GB 10000r Ultra3 SCSI disk 1"
2	201202-421	1 ProLiant DL580 G2 2P 1400MHz 2GB 4U rack
2.1	176496-B22	4 36GB 10000r Ultra3 SCSI disk 1"
2.2	202171-B21	1 2GB PCI1600 Reg. ECC SDRAM (4x512MB)
2.3	226775-B21	2 Pentium III Xeon 1400-512KB processor ki
2.4	245299-B21	2 MSA1000 FC HBA FCA2101 for WNT/W2k 2GB
3	201202-421	1 ProLiant DL580 G2 2P 1400MHz 2GB 4U rack
3.1	176496-B22	4 36GB 10000r Ultra3 SCSI disk 1"
3.2	202171-B21	1 2GB PCI1600 Reg. ECC SDRAM (4x512MB)
3.3	226775-B21	2 Pentium III Xeon 1400-512KB processor ki
3.4	245299-B21	2 MSA1000 FC HBA FCA2101 for WNT/W2k 2GB
4	201203-421	1 ProLiant DL580 G2 2P 1600MHz 2GB 4U rack
4.1	176496-B22	4 36GB 10000r Ultra3 SCSI disk 1"
4.2	202171-B21	3 2GB PCI1600 Reg. ECC SDRAM (4x512MB)
4.3	226776-B21	2 Pentium III Xeon 1600-1MB processor kit
4.4	245299-B21	2 MSA1000 FC HBA FCA2101 for WNT/W2k 2GB
5	201203-421	1 ProLiant DL580 G2 2P 1600MHz 2GB 4U rack
5.1	176496-B22	4 36GB 10000r Ultra3 SCSI disk 1"
5.2	202171-B21	3 2GB PCI1600 Reg. ECC SDRAM (4x512MB)
5.3	226776-B21	2 Pentium III Xeon 1600-1MB processor kit
5.4	245299-B21	2 MSA1000 FC HBA FCA2101 for WNT/W2k 2GB
6	231892-B22	2 MSL5026 SDLT Lib.2xDrive,RackM,LVD
7	218241-B21	1 Mod. Data Router 2xFC,4xLVD,4xGBIG,2x5m
8	213076-B22	4 Secure Path V3.1B for Windows W-Group
9	231824-B21	1 MSL5026 Pass-Thorough Mechanism
10	341175-B21	3 VHDCI to VHDCI SCSI Cable 12ft
11	221692-B21	8 PC ShortWave 2m cable LC-LC (MSA1000)
12	119826-B21	2 Modula M42/314R 2nd power supply




- 221692-B21 LC-LC 2m
- 221692-B21 LC-LC 2m
- 221692-B21 LC-LC 2m
- 221692-B21 LC-LC 2m

- 221692-B21 LC-LC 2m
- 221692-B21 LC-LC 2m
- 221692-B21 LC-LC 2m
- 221692-B21 LC-LC 2m





RAID MSA1000

Modular Data Router 2FC LVD

MSL5026 SDLT Library,Rack LVD



6x7 x72.8GB = 3TB



www.Compaq.com/golden-eggs

Since:May-2002

COMPAQ	07-May-2002	GTIDL580e
	Matti.Patari@Compaq.com	

ProLiant DL580 G2 MSA1000 SAN
GOLDEN EGGS Visuals, Helsinki