



**Compaq ProLiant DL760 8P**



DL760




M4354R



M4314R



M4314R





SCSI cables VHDCI - VHDCI  
12ft included in M43xx

119826-B21 2nd pwr  
119826-B21 2nd pwr

Bill of material


Part Number	Qty	Description
1	1	212692-421 1 ProLiant DL760 4P 900MHz 2GB rack 7U
1.1	1	157866-021 1 CPQ Remote Insight manager kit
1.2	1	158939-B21 1 Smart Array 5304/128MB,Ultra3 4-chan
1.3	4	177666-B21 4 Pentium III Xeon 900-2MB processor kit
1.4	4	232916-B22 4 36GB 15000r Ultra3 SCSI disk 1"
1.5	6	328809-B21 6 2GB 100MHz ECC SDRAM DIMM(2x1024MB)
2	1	190209-B31 1 Modula M4314R single buss,14x 1.0"
2.1	10	176496-B22 10 36GB 10000r Ultra3 SCSI disk 1"
3	1	190209-B31 1 Modula M4314R single buss,14x 1.0"
3.1	14	176496-B22 14 36GB 10000r Ultra3 SCSI disk 1"
4	1	190211-B31 1 Modula M4354R dual buss, 7+7, 1.0"
4.1	8	232432-B22 8 72.8GB 10000r Ultra3 SCSI disk 1"
5	2	119826-B21 2 Modula M42/314R 2nd power supply



DL760



M4354R



SCSI cables VHDCI - VHDCI  
12ft included in M43xx

Bill of material

Part Number	Qty	Description
1	1	212692-421 1 ProLiant DL760 4P 900MHz 2GB rack 7U
1.1	1	124992-B21 1 Smart Array 5302/64MB,Ultra3 2-chan
1.2	1	157866-021 1 CPQ Remote Insight manager kit
1.3	4	177666-B21 4 Pentium III Xeon 900-2MB processor kit
1.4	1	216886-B21 1 35/70GB Hot plug AIT tape drive
1.5	2	232916-B22 2 36GB 15000r Ultra3 SCSI disk 1"
1.6	2	328808-B21 2 1GB 100MHz ECC SDRAM DIMM(2x512MB)
2	1	190211-B31 1 Modula M4354R dual buss, 7+7, 1.0"
2.1	8	232432-B22 8 72.8GB 10000r Ultra3 SCSI disk 1"

[www.Compaq.com/golden-eggs](http://www.Compaq.com/golden-eggs)  
Since:Nov-2001

<b>COMPAQ</b>	28-Nov-2001	GTIDL760a
	Matti.Patari@Compaq.com	

ProLiant DL760 4P Entry System  
GOLDEN EGGS Visuals, Helsinki