






Compaq ProLiant ML570 2P/1P



SCSI cables VHDCI - VHDCI  
12ft included in M43xx

Bill of material

	Part Number	Qty	Description
1	138662-421	1	ProLiant ML570 1P 700MHz 512MB rack 7U
1.1	124992-B21	1	Smart Array 5302/64MB,Ultra3 2-chan
1.2	128248-B21	1	ML570 Hot plug blower kit, 2x fans
1.3	128286-021	1	ML570 R02 second power supply, Int
1.4	157766-B21	2	50GB AIT tape drive, Internal
1.5	157866-021	1	CPQ Remote Insight manager kit
1.6	174448-B21	3	Pentium III Xeon 700-1MB processor kit
1.7	189080-B21	3	512MB PC100 CL2 ECC SDRAM (4x128MB)
1.8	232916-B22	8	36GB 15000r Ultra3 SCSI disk 1"

Bill of material

	Part Number	Qty	Description
1	155606-423	1	ProLiant ML570 2P 900MHz 1GB rack 7U
1.1	124992-B21	1	Smart Array 5302/64MB,Ultra3 2-chan
1.2	128248-B21	1	ML570 Hot plug blower kit, 2x fans
1.3	128286-021	1	ML570 R02 second power supply, Int
1.4	157766-B21	2	50GB AIT tape drive, Internal
1.5	157866-021	1	CPQ Remote Insight manager kit
1.6	158939-B21	1	Smart Array 5304/128MB,Ultra3 4-chan
1.7	189081-B21	3	1GB PC100 CL2 ECC SDRAM (4x256MB)
1.8	222627-B21	2	Pentium III Xeon 900-2MB processor kit
1.9	232916-B22	12	36GB 15000r Ultra3 SCSI disk 1"
2	190209-B31	1	Modula M4314R single buss,14x 1.0"
2.1	176496-B22	10	36GB 10000r Ultra3 SCSI disk 1"
3	190209-B31	1	Modula M4314R single buss,14x 1.0"
3.1	176496-B22	14	36GB 10000r Ultra3 SCSI disk 1"
4	190211-B31	1	Modula M4354R dual buss, 7+7, 1.0"
4.1	232432-B22	8	72.8GB 10000r Ultra3 SCSI disk 1"
5	119826-B21	2	Modula M42/314R 2nd power supply

ML570 4P

<b>COMPAQ</b>	18-Dec-2001	GTIML570a
	Matti.Patari@Compaq.com	
ProLiant ML570 2P Entry System GOLDEN EGGS Visuals, Helsinki		