





Compaq ProLiant ML570 2P/1P



Bill of material

Part Number	Qty	Description
1	1	180320-421 ProLiant ML570 G2 1P 1400MHz 512k 512MB
1.1	1	187418-B21 512MB PCI1600 ECC SDRAM (2x256MB)memory
1.2	1	226775-B21 Intel Xeon MP 1400-512KB processor kit
1.3	1	227251-021 Remote Insight Lights-Out Edition II EU
1.4	1	244948-B21 Compaq NC7770 PCI-X Gigabit Server Adapt
1.5	1	249189-B21 100GB AIT tape drive, Internal
1.6	1	283552-B21 Smart Array 5302/128MB,Ultra3 2-chan
1.7	8	3R-A3848-AA 18.2GB 15000r U320 SCSI disk 1"

Bill of material

Part Number	Qty	Description
1	1	191694-421 ProLiant ML570 G2 2P 2000MHz 2MB 1GB rac
1.1	3	187419-B21 1GB PCI1600 ECC SDRAM (2x512MB)memory
1.2	1	227251-021 Remote Insight Lights-Out Edition II EU
1.3	1	236844-B21 ML570 Hot Plug Memory Expansion Board
1.3.1	2	187419-B21 1GB PCI1600 ECC SDRAM (2x512MB)memory
1.4	1	244948-B21 Compaq NC7770 PCI-X Gigabit Server Adapt
1.5	2	249189-B21 100GB AIT tape drive, Internal
1.6	1	283551-B21 Smart Array 5304/256MB,Ultra3 4-chan
1.7	1	283552-B21 Smart Array 5302/128MB,Ultra3 2-chan
1.8	12	286778-B22 72.8GB 15000r U320 disk 1"
1.9	2	307276-B21 Intel Xeon MP 2000-2MB processor kit
2	1	190209-B31 Modula M4314R single buss,14x 1.0"
2.1	10	176496-B22 36GB 10000r Ultra3 SCSI disk 1"
3	1	190209-B31 Modula M4314R single buss,14x 1.0"
3.1	14	176496-B22 36GB 10000r Ultra3 SCSI disk 1"
4	1	190211-B31 Modula M4354R dual buss, 7+7, 1.0"
4.1	8	232432-B22 72.8GB 10000r Ultra3 SCSI disk 1"
5	2	119826-B21 2nd power supply

Generated with fresh GOLDEN EGGS Software, Rev:17-Jan-2003

www.Compaq.com/golden-eggs

Since:Dec-2001

	17-Jan-2003	GTIML570G2a
	Matti.Patari@hp.com	

ML570 4P

ProLiant ML570 G2 entry systems
GOLDEN EGGS Visuals, Helsinki